

Top 50 Etab Shortcut Commands

1. Ctrl + N: Create a new model
2. Ctrl + O: Open an existing model
3. Ctrl + S: Save the current model
4. Ctrl + P: Print the current view
5. Ctrl + Z: Undo the last action
6. Ctrl + Y: Redo the last undone action
7. Ctrl + A: Select all entities
8. Ctrl + X: Cut selected entities
9. Ctrl + C: Copy selected entities
10. Ctrl + V: Paste copied entities
11. Ctrl + F: Find an entity or text in the model
12. Ctrl + G: Find next occurrence of searched entity or text
13. Ctrl + H: Replace entity or text in the model
14. Ctrl + E: Export model to various formats
15. Ctrl + I: Import data into the model
16. Ctrl + M: Toggle measurement mode
17. Ctrl + B: Toggle section view mode
18. Ctrl + D: Toggle dimension display
19. Ctrl + R: Toggle render mode
20. Ctrl + T: Toggle transparency
21. Ctrl + L: Toggle layer visibility
22. Ctrl + K: Toggle snap mode
23. Ctrl + J: Toggle joint visibility
24. Ctrl + W: Close the current view
25. Ctrl + Q: Quit Etab
26. Ctrl + Shift + Z: Redo multiple actions
27. Ctrl + Shift + A: Add a new entity
28. Ctrl + Shift + C: Create a new section cut
29. Ctrl + Shift + E: Edit an entity
30. Ctrl + Shift + F: Add a free node
31. Ctrl + Shift + G: Group selected entities
32. Ctrl + Shift + I: Insert an entity
33. Ctrl + Shift + L: Load or unload a layer
34. Ctrl + Shift + M: Modify an entity
35. Ctrl + Shift + P: Add a point load
36. Ctrl + Shift + R: Add a reaction
37. Ctrl + Shift + S: Add a support
38. Ctrl + Shift + T: Add a member property
39. Ctrl + Shift + U: Add a uniform load
40. Ctrl + Shift + X: Add a section cut by extrusion
41. Alt + Enter: View entity properties
42. Alt + F4: Close the current window

43. Alt + F10: Maximize the current window
44. Alt + Tab: Switch to the next window
45. F1: Open the help file
46. F2: Rename a selected entity
47. F3: Show the element connectivity
48. F4: Show/hide the grid
49. F5: Refresh the current view
50. F6: Show/hide the screen tips